


HSS



$d1$ mm	$d2$ mm	L mm	l mm
1,00	3,15	31,50	1,60
1,25	3,15	33,50	1,90
1,60	4,00	37,50	2,40
2,00	5,00	42,00	2,90
2,50	6,30	47,00	3,60
3,15	8,00	52,00	4,40
4,00	10,00	59,00	5,60
5,00	12,50	66,00	6,90
6,00	16,00	74,00	8,60
10,00	25,00	100,00	31,50
12,50	31,50	125,00	33,50